


Parts needed to mount the KOZEL-50 extrusion



Tools needed for mounting:

- mounting glue

The **TECH-50 PROTECTIVE INSERT** ensures that the profile slot remains wide enough for the snap-in cover (its use is NECESSARY during mounting and finishing works).

NOTE! All LED strips must be connected to a 12 V or 24 V power supply.

IMPORTANT: The manual presents the simplest mounting procedure. More mounting procedures and related accessories can be found at klusdesign.eu



