

Parts needed to mount the TRIADA-K extrusion



Tools needed for mounting:

- mounting glue

NOTE! All LED strips must be connected to a 12 V or 24 V power supply.

IMPORTANT: The manual presents the simplest mounting procedure.


More mounting procedures and related accessories can be found at www.klusdesign.eu


www.klusdesign.eu 1




 $\pmb{1}_{\bullet}$ Install the LED strips (B) in the extrusion (A), insert the covers (C) and the end caps (D).

2. Feed the power cable. Spread the glue inside the mounting groove.





 ${\bf 3.}$ Connect power to the LED strip and mount the extrusion (A) in the mounting groove.



www.klusdesign.eu 2