


1. Attach the mounting bracket to the surface with screws.

2. Bend back one side of the mounting bracket and insert the extrusion



NOTE! A list of products corresponding with the selected accessories is available at www.KlusDesign.eu