

Parts needed to mount the KRAV-05IN profile



Profile (A)



End cap (B)




LED strip (C)


NOTE! All LED strips must be connected to a 12 V or 24 V power supply.

IMPORTANT: The manual presents the simplest mounting procedure. More mounting procedures and related accessories can be found at klusdesign.eu


1. Attach the LED strip (C) to the lower part of the profile (A) with glue and insert the power cable.




2. Degrease the glass and attach the upper part of the profile (A).



3. Attach the lower part of the profile (A) with glue.



4. Insert the end caps (B).



5. Connect power.

